

James M. Welsch Station Director Diablo Canyon Power Plant Mail Code 104/5/502 P. O. Box 56 Avila Beach, CA 93424

805.545.3242 Internal: 691.3242 Fax: 805.545.4234 Internet: JMW1@pge.com

PG&E Letter DCL-2013-503

Certified/Return Receipt # 7010-1060-0000-4204-4500

January 31, 2013

Sarah Wilkin Stranding Coordinator National Marine Fisheries Service 501 West Ocean Blvd., Suite 4200 Long Beach, California 90802-4213

2012 Annual Sea Turtle Report for Diablo Canyon Power Plant (DCPP)

Dear Ms. Wilkin,

As required by the biological opinion (issued: September 18, 2006) generated by Nuclear Regulatory Commission (NRC) biologists and National Oceanographic and Atmospheric Administration (NOAA) Fisheries staff, the enclosed annual report summarizes sea turtles observed in the vicinity of DCPP during 2012.

One small green sea turtle was found in an intake structure forebay on September 21, 2012. The turtle was released to the open ocean unharmed on the same day. No other sea turtles were observed in the vicinity of DCPP during 2012.

If you have any questions or concerns regarding the enclosed report, or require additional information, please contact James Kelly at (805) 545-3194.

Sincerely,

James M. Welsch

Station Director, Diablo Canyon Power Plant

2013503/jlk

Enclosures (1)

IE25 NRR PG&E Letter DCL-2013-503 Sarah Wilkin, NMFS January 31, 2013 Page 2

cc: Alan B. Wang
NRR Project Manager
U.S. Nuclear Regulatory Commission
One White Flint North
Mail Stop 7 E1
11555 Rockville Pike
Rockville, MD 20852-2738

Thomas Hipschman
Senior Resident Inspector
U.S. Nuclear Regulatory Commission
Diablo Canyon Power Plant 104/5

Regional Administrator U.S. Nuclear Regulatory Commission Region IV 612 E. Lamar Blvd., Suite 400 Arlington, TX 76011-4125

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555-0001

ENCLOSURE 1

2012 ANNUAL SEA TURTLE REPORT FOR DIABLO CANYON POWER PLANT

PACIFIC GAS AND ELECTRIC COMPANY NUCLEAR POWER GENERATION

2012 Annual
Sea Turtle Report
For
Diablo Canyon Power Plant

PACIFIC GAS AND ELECTRIC COMPANY

2012 ANNUAL SEA TURTLE REPORT FOR DIABLO CANYON POWER PLANT

TABLE OF CONTENTS

	page
Incidental Take Reports	. 1
Intake Inspection Records	. 1
Sea Turtle Observations	. 1
Status of DCPP Incidental Take Level	1
Actions to Reduce Sea Turtle Entrainment	2
Appendix 1: Incidental Take Report – October 17, 2012 Appendix 2: Intake Inspections	

INCIDENTAL TAKE REPORTS

One green sea turtle was discovered in DCPP's intake structure on September 21, 2012. The live, healthy and uninjured, sea turtle was measured, tagged, and released unharmed about one mile offshore of the power plant on the same day. A copy of the sea turtle stranding report submitted to the National Marine Fisheries Service (NMFS) on October 17, 2012 is included in Appendix 1.

INTAKE INSPECTION RECORDS

In the 24-hours prior to the incidental take of the green sea turtle in September 2012, Intake Operators inspected the intake forebays approximately every 12 hours. A summary table of the inspections conducted during this time period is included in Appendix 2.

SEA TURTLE PHOTOGRAPHS

Several photographs were taken of the green sea turtle found in DCPP's intake structure September 21, 2012. Four photographs of the turtle were incorporated in the stranding report submitted to the NMFS on October 17, 2012 (Reference Appendix 1).

SEA TURTLE OBSERVATIONS

Biological monitoring and other activities occurred routinely in the waters around DCPP throughout 2012. Other than the green sea turtle found in the power plant intake structure in September, there were no other sea turtles observed in the vicinity of DCPP during 2012.

STATUS OF DCPP INCIDENTAL TAKE LEVEL

DCPP's 2006 Incidental Take Statement allows the following levels of sea turtle take for the period 2007 through 2026.

Species	Total Entrainment	Mortality	Serious Injury
Green	15 turtles	3 turtles	1 turtle
Leatherback	3 turtles	1 turtle	1 turtle
Loggerhead	3 turtles	1 turtle	1 turtle
Olive Ridlev	3 turtles	1 turtle	1 turtle

Sea turtles taken and released since 2006: Four healthy green sea turtles (one in 2007, one in 2009, one in 2010, and one in 2012).

As four healthy green sea turtle were taken and released since 2006, DCPP has eleven remaining allowed green sea turtle takes for 2013 through 2026. Leatherback, Loggerhead, and Olive Ridley allowed takes remain at three. There have been no sea turtle mortalities or serious injuries.

ACTIONS TO REDUCE SEA TURTLE ENTRAINMENT

DCPP took no specific direct actions to reduce sea turtle entrainment during 2012. Sea turtles continue to be rare in the vicinity of the power plant. In addition, all incidental takes to date have been live, healthy and uninjured, sea turtles that were released unharmed.

Signs reminding operations and maintenance personnel to watch for turtles during inspection rounds were installed at the intake in early 2007, and remained in place throughout 2012.

APPENDIX 1

Sea Turtle Incidental Take Report

October 17, 2012 (5-Pages)



Pacific Gas and Electric Company Diablo Canyon Power Plant P.O. Box 56 Avila Beach, CA 93424

PG&E Letter DCL-2012-538

Certified/Return Receipt 7010-1060-0000-4204-4340

October 17, 2012

Sarah Wilkin, Stranding Coordinator National Marine Fisheries Service 501 West Ocean Blvd., Suite 4200 Long Beach, California 90802-4213

Dear Ms. Wilkin:

Enclosed is a National Marine Fisheries Service (NMFS) Marine Mammal and Marine Turtle Stranding Report for a sea turtle discovered in the Diablo Canyon Power Plant (DCPP) intake structure.

A live sea turtle was discovered in the 1-2 intake structure forebay by plant operations personnel at approximately 3:45 p.m. on September 21, 2012. The turtle was identified as a green sea turtle (*Chelonia mydas*).

As authorized in DCPP's incidental take statement issued September 18, 2006, DCPP staff removed the turtle from the intake structure that afternoon (September 21, 2012) for release offshore of the facility. The turtle was removed by salmon net and transported to a facility boat. The plant biologist completed measurements of the specimen, and photographs were taken. The photographs are enclosed in addition to the stranding report. The turtle was estimated to weigh 18 pounds, with a shell length (notch-tip) of 19 inches, and appeared to be in good health based on visual observation. There were no abrasions or indication of any injury. The turtle was tagged on the left front flipper with tag #MC-0, and subsequently transported by boat and released in the ocean approximately one mile southwest of DCPP. The turtle swam away strongly in a southerly direction following release.

Discovery and release of the turtle was reported to NMFS via telephone on September 21, 2012, within the required 48-hour reporting period.

Live green sea turtles have been discovered at DCPP's intake on ten previous occasions during commercial operations: August 08, 2010, September 08, 2009, July 23, 2007, February 27, 2001, April 16, 2000, August 24, 1999, May 29, 1999, June 12, 1997, January 10, 1997, and April 27, 1994. Green sea turtles are infrequently observed in the coastal waters off of DCPP.



PG&E Letter DCL-2012-538 Sarah Wilkin, NMFS October 17, 2012 Page 2

If you have any questions or concerns regarding the enclosed report, or require additional information, please contact Jim Kelly of my staff at (805) 545-3194.

Sincerely,

Kenneth W. atur

Kenneth W. Cortese

Manager - Chemistry and Environmental Operations

2012538/jlk/bkc

Enclosures (2)

cc w/enclosures:

Alan B. Wang

NRR Project Manager

U.S. Nuclear Regulatory Commission

One White Flint North

Mail Stop 08B1

11555 Rockville Pike

Rockville, MD 20852-2738

Laura Micewski Resident Inspector

U.S. Nuclear Regulatory Commission Diablo Canyon Power Plant 104/5

Regional Administrator

U.S. Nuclear Regulatory Commission

Region IV

612 E. Lamar Blvd., Suite 400 Arlington, TX 76011-4125

U.S. Nuclear Regulatory Commission

Document Control Desk

Washington, D.C. 20555-0001

Marine Region


California Department of Fish and Game

20 Lower Ragsdale Dr. Suite 100

Monterey, CA 93940

MARINE MAMMAL AND MARINE TURTLE ST	RANDING REPORT SID#(NMFS_USE)
FIELD NO.:	NMTS REGISTRATION NO.
COMMON NAME: Green Sea Turtle GENT	JS: Chelonia SPECIES: mydas
EXAMINER James L. Kelly	Agency: Pacific Gas & Electric Co. Phone: (805) 545-3194
Address: Diablo Canyon Power Plant	(DCPP), P.O. Box 56, Avila Beach, California 93424
LOCATION San Luis State: CA County: Obispo City: Avila Beach Locality Details: Diablo Canyon Power Plant (DCPP) 9-Miles NW of Avila Beach. 1-2 Forebay Bar Rack of the Plant Intake Structure. *Latitude: 35° 12' 44" N *Longitude: 120° 51' 13"	
DATE OF INITIAL OBSERVATION:	DATE OF EXAMINATION:
Yr 2012 Mo September Day	21 Yr 2012 Mo September Day 21 CONDITION: Check one: X1.Alive d
LIVE ANIMAL - Condition and Dispos Check one X 1.Released at site or more:2.Sick	TAGS PRESENT?: (Yes) / (No) Dorsal Left Right Tag No.(s): MC-0 eleased Color(s): Silver Type: Flipper
(bled) / (keleased) bate: ochtcimbe	r 21, 2012 Placement Front/Rear Front/Rear
CARCASS - Disposition, check one: Check one:1.Left at site	
DEMARKS. Straight Width /Widest Do	oint) 18 & 1/2 inches; Tail Length 1 inch.
A Lepas Barnacle was attached to t	the right edge of shell 1/3 of the length back from the ed strong and healthy. No abrasions. No indications of
JISPOSITION OF TISSUE/SKELETAL MAT	ERIAL:
	·
OMB#0648-0178	It is estimated that completion of this form requires 20 minutes.


Specimen Photographs - Green Sea Turtle (*Chelonia mydas*)
Diablo Canyon Power Plant - September 21, 2012





Specimen Photographs - Green Sea Turtle (*Chelonia mydas*)
Diablo Canyon Power Plant - September 21, 2012





APPENDIX 2

Intake Inspection Records
September 20-21, 2012
(1-Page)

DCPP Intake Bar Rack Inspection Times During the 24-Hour Period Prior to Sea Turtle Sighting on September 21, 2012

			Operator	
Date	Unit 1	Unit 2	ID	Condition
9/20/2012	0:49	0:49	Bigelow	SAT
9/20/2012	9:39	9:39	Auleb	SAT
9/20/2012	21:45	22:19	Batalla	SAT
9/21/2012	13:06	13:06	Neal	SAT
9/21/2012	15:45	15:45	Neal	One Turtle

SAT = Satisfactory - no turtles, kelp at acceptable levels, bar racks satisfactory condition.

Detailed shift operator logs are available at the facility which incorporate the intake inspections listed in the table above that were conducted September 20, 2012 and September 21, 2012.